



APG LIVE MANAGER RELEASE NOTES

v1.8

Bug fixes

- Incomplete “Reset to factory settings” on Input parameters
- “Pairing” feature would display improper preset names with presets from the machine internal library
- “Load session from file” would display improper preset names with presets from the machine internal library
- “Reset EQ” feature would reset bypassed bands
- Inversion on blinking MUTE LED state when member of a group is muted/unmuted

New features

- Firmware update
- Internal machine presets bank initialisation
- Various cosmetic and ergonomic improvements

v1.7.3

Bug fixes

- Modules mute buttons would blink as soon as module is a member of a group
- Reset to factory settings loads a wrong value of Vx limiter threshold. Factory init activates protections too early on init preset

v1.7.2

Bug fixes

- “Delete Group” feature doesn’t always remove all overlays in machines
- Unrelated Output channels linked together when stereo link is active
- “Load session from file” feature forces user to apply parameters on each machine individually
- “Load session from file” feature doesn’t load machine names properly
- “Stereo link” feature causes machine to go to Network Conflict state at every disconnection

New features

- Save/Load of individual machine configurations with*.almmc files
- Display of groups EQ summation curve on each module EQ curve
- “Reset” feature on EQ
- New SB series presets (SB110, SB112, SB115-M2)
- Legacy presets (DS18, DS12S, DS15, DS15S, DS15R)
- Improved stability
- Various cosmetic and ergonomic improvements
- Crash reports saved into logs folder

v1.7.1

Bug fixes

- Autoupdate feature was disabled since v1.5.1

v1.7.0

Bug fixes

- Minor issues

New features

- Sleep all/Wake all amplifiers to activate/deactivate the Deep Power Save Mode on DA series
- Fallover priority selection on input type for DA series
- Bridge mode on DA series



- Global bypass on EQ
- Advanced limiter settings available on FLAT preset
- More cardioid configurations available in preset library
- Improved stability
- Various cosmetic and ergonomic improvements

v1.6.0

Bug fixes

- Application crash after editing the same parameter on two or more consecutive outputs
- Machine panel is positioned out of the visible workspace area when retrieved from network after use in System Engineer
- Wrong activation code cannot be overwritten by user

New features

- Confirmation message upon adding machine to the session and flush overlays

v1.5

Bug fixes

- Application starts without opening the main window, process has to be terminated manually
- DMS48 Automatic reboot due to network request overflow
- Group name editing is disabled in v1.4

New features

- Mute all/Unmute all
- Various ergonomic improvements